

Rapor 1



Company:	Sanpa
Address:	Sanpa
City:	İstanbul
Tel:	0 212 297 70 00
E-mail:	info@sanpaelektronik.com

Instrument references

Manufacturer:	
Model:	ST-982
Serial number:	180107023

Customer Information

Customer:	X
Address:	Sanpa
City:	İstanbul
Measurement:	Panel
Measuring Address:	İstanbul
Measurement City:	İstanbul



IR image & Visible image

GENERAL INFORMATIONS

File name:	20180326_0002.JPG		
Date of saved image:	2018-03-26	Emissivity value:	0,95
Hour of saved image:	17:16:24	Ambient temperature:	25,0°C
Max temp value:	12,9°C	Reflected Temperature:	25,0°C
Min temp value:	-5,6°C	Humidity:	50%
AVE Temp.	7,3°C	Distance:	5,0m

Measure Description:


2018-03-26

Rapor 1




“BURAYA ÇEKTİĞİNİZ RESİMLERLE İLGİLİ BİLGİLER YAZABİLİRSİNİZ”

ADVANCED ANALYSIS



Details of Rectangle included on IR image

NO.	AVE Temp.	Maximum	Minimum	Emissivity	Reflected Temperature	Ambient Temperature	Humidity	Distance
R1	10,2°C	12,9°C	-2,8°C	0,95	25,0°C	25,0°C	50%	5,0m



Summarize The Contents: